

	Service Bulletin: ParagonX Software Update		
Prepared by: Maxwell Anderson	Date Prepared: 3/10/2022	Models Affected: ParagonX (TM733)	Bulletin Number: NB-2203012

DESCRIPTION

An update for the Horizon ParagonX (TM733) is now available. The software addresses the following.

- Fixes a bug that causes the console to crash when connecting a wireless Polar heart rate monitor
- The target heart rate program has been updated to more quickly detect when the console has lost connection with a wireless heart rate monitor

Please update your console according to the matrix below as software versions are UCB dependent.

<u>UCB#</u>	<u>New Software Version</u>	<u>Previous Software Version</u>
1000466018 (@Zone UCB)	V1.08	V1.06
1000449623 (USB Port UCB)	V6.31	V6.24
1000417030 (No USB Port UCB)	V5.41	V5.33